LOCAL NOTICE TO MARINES NO 25

WEEKLY SUPPLEMENT - JUNE 1997

**FAX-ON-DEMAND - LOCAL NOTICE TO MARINERS AT (703) 313-5931 or 5932 **

** Electronic Bulletin Board Service: (703) 313-5910 **

300 to 28.8 bps, 8 data bite, no parity 1 stop bit NIS watchstander, 24 hours a day at (703) 313-5900 ~ INTERNET ADDRESS ~ http://www.navcen.uscg.mil

OR

ftp://ftp.navcen.uscg.mil

Issued by: Commander (mon) Telephone: (907) 463-2262 (0800-1600)

Seventeenth Coast Guard District

(907) 463-2004

Facsimile:(907) 4632273

(1600-0800)

P.O. Box 25517

Juneau, AK 998025517

Questions comments or additional information on this Local Notice to Mariners or the Local Notice to Mariners mailing list (additions, deletions, corrections) should be directed to the address above.

For faster service, get the 17~ District Local Notice to Mariners via e-mail. To get on our electronic mailing list, send us an e-mail at: akcgnav@alaska.net

LIGHT LIST REFERENCE: COMDTPUB P16502.6 VOLVI 1996 EDITION

BROADCAST NOTICE TO MARINERS

Navigation information previously promulgated by Broadcast Notice to Mariners 161/97 through 264/97 and still in effect is included in this notice.

USE OF THE LOCAL NOTICE TO MARINERS

The Weekly Supplemental editions contain new information available subsequent to the issue of the Monthly edition. To ensure having complete information concerning the waterways of the

Seventeenth Coast Guard District, consult Monthly edition 19/97.

I SPECIAL NOTICES

GUSTAVUS-DGPS-OFF-AIR

The DGPS signal from the Gustavus DGPS site will be off-air during the period of 1600Z 19 June 97 to 0200Z 20 June 97.

POTATO POINT- DGPS- OFF-AIR

The Potato Point DGPS site is authorized intermittent off-air periods between 1500Z and 0400Z on 08, 09, 24, and 25 July 97.

Date:17 JUNE 1997 1
Notice Number 25

17 JUNE 1997

LOCAL NOTICE TO MARINES NO 25

KODIAK-LORANC-PROPOSED OFFAIR

This is a proposal to authorize Loran Station Kodiak (796(K/9990-Z)) off-air time from 1800Z to 2000Z on 19 Jun 1997. The alternate time will be from 1800Z to

2000Z on 25 Jun 1997. Objections will be considered until 1800Z on 13 Jun 1997. Users shall address inquiries to the North Pacific Coordinator of Chain Operations at (907) 48-\$\overline{7}\$183. Current Loran-C status is available 24 hours a day through an electronic bulletin board system (BBS) at (703) 31-\$\overline{5}\$910, baud rate 300 to 28,800. Communications parameters are eight bit word, one stop bit, no parity. Internet address: http://hAnNw.navcen.uscg.mil

SAINT PAUL- LORAN-C - PROPOSED OFFAIR

This is a proposal to authorize Loran Station Saint Paul (9990-M) offir time from 1800Z to 2000Z on 19 Jun 1997. The alternate time will be from 1800Z to

2000Z on 25 Jun 1997. Objections will be considered until 1800Z on 13 Jun 1997. Users shall address inquiries to the North Pacific Coordinator of Chain Operations at (907) 48-\$\overline{7}\$183. Current Loran-C status is available 24 hours a day through an electronic bulletin board system (BBS) at (703) 31-\$\overline{5}\$910, baud rate 300 to 28,800. Communications parameters are eight bit word, one stop bit, no parity. Internet address: http://hAnNw.navcen.uscg.mil

PORT CLARENCE- LORAN-C - PROPOSED OFFAIR

This is a proposal to authorize Loran Station Port Clarence (7960-Z/9990-Y) offir time from 1800Z to 2000Z on 19 Jun 1997. The alternate time will be from 1800Z to 2000Z on 25 Jun 1997. Objections will be considered until 1800Z on 13 Jun 1997. Users shall address inquiries to the North Pacific Coordinator of Chain Operations at (907) 487-5183. Current Loran-C status is available 24 hours a day through an electronic bulletin board system (BBS) at (703) 313-5910, baud rate 300 to 28,800. Communications parameters are eight bit word, one stop bit, no parity. Internet address: http://hAnNw.navcen.uscg.mil

REPORT DEFECTS IN AIDS TO NAVIGATION TO THE NEAREST COAST GUARD UNIT

I SPECIAL NOTICES (Cont)

ALASKA - SOUTHEAST - BEHM CANAL - SPILL RESPONSE EXERCISE

The U.S. Coast Guard will be conducting a Spill Response Exercise iBehm Canal from Mountain Point north to the vicinity of Shoal Cove, Alaska. Activities are scheduled daily from 0730-1700 on June 23 through June 26,1997. Vessels involved include USCG@lanetree, Canadian CCG's Sir Winfred Laurier and Kitimat II and the M/V Big Tow 1. The exercise should not interfere with vessel traffic. Vessels involved will be towing booms and inflatable barges. A Coast GuardAuxilary vessel will be in the vicinity while the exercise is conducted. Vessels in the exercise will be standing by on VHF channels 13 and 16. Any questions should be directed to Marine Safety Office Juneau (907) 463-2245, or Mr. Ric Lanelle at the District 17 Response Advisory Team at (907) 463-2247.

Date:17 JUNE 1997 2

17 JUNE 1997

LOCAL NOTICE TO MARINES NO 25

II DISCREPANCIES - DISCREPANCIES CORRECTED

DISCREPANCIES:

| LLNR NAME OF AID | STATUS | CHART | BNM | LNM |
|-----------------------------------------|----------------------------|--------------|--------|-------|
| 22429.5 Thorne Bay ChannelDaybeacon "7" | Destroyed | 17405 | 657/96 | 48/96 |
| 23801 Coghlan IslandDaybeacon "1" | Partially Destroyed | 17315 | 187/97 | 21/97 |
| 26100 East Amatuli Island Light | Dayboard Destroyed | 16640 | 199/97 | 23/97 |
| 27810 Ekuk Range Front Light | Dayboard Improper Characte | ristic 16591 | 205/97 | 23/97 |
| | | | | |
| LLNR NAME OF AID | STATUS | CHART | BNM | INM |

DISCREPANCIES/PRIVATE AIDS:

| LLNR NAME OF AID | STATUS | CHART | BNM | LNM |
|-------------------------------|--------------|-------|--------|-------|
| 27467 APL Dolphin Lights | Extinguished | 16011 | 178/97 | 20/97 |
| 27467 APL Shoal Lighted Buoys | Extinguished | 16011 | 178/97 | 20/97 |

III TEMPORARY CHANGES - TEMPORARY CHANGES CORRECTED TEMPORARY CHANGES:

| LLNR | NAME OF AID | STATUS | CHART | BNM | LNM |
|---------|--------------------------------|-----------|-------|--------|-------|
| 1105 | Cape St.Elias Bell Buoy "2" | TUB | 16723 | 121/97 | 13/97 |
| 23305.6 | Keku Strait Daybeacon "9" | TRUB | 17372 | 188/97 | 21/97 |
| 23305.8 | Keku Strait Daybeacon "11" | TRUB | 17372 | 188/97 | 21/97 |
| 26250 | Anchor Point Light | FIW 6s 7M | 16645 | 437/96 | 30/96 |
| 25645 | Knowles HeadLigted Bell Buoy 4 | TRLWB | | 257/97 | 25/97 |

IV CHART CORRECTIONS

| 16640 22 nd Ed 1/08/94 Last LNM 33/96 NAD 83 25/97 | | | (CCGD17) | |
|---------------------------------------------------------------|-----------------------------------------|----------------------------|--------------|--|
| | AK -Cook Inlet - So | outhern Part | | |
| | delete: | Buoy '2' | 59°29'30.9"N | |
| 151°3 | 3'12.2"W | , - | | |
| | add: | Daybeacon '2' | 59°29'29.2"N | |
| 151°3 | 3'17.2"W | , | | |
| | | | | |
| 16645 | 17 th Ed1/25/97 Las 25/97 | st LNM 24/97 NAD 83 | (CCGD17) | |
| | AK -South Coast - | Gore Point to Anchor Point | | |
| | delete: | Lighted Buoy '1' | 59°26'51.7"N | |
| 151°4 | 3'25.6"W | · · | | |
| | | Buoy '2' | 59°29'30.9"N | |
| 151°3 | 3'12.2"W | | | |
| | add: | Light '1' | 59°26'52.0"N | |
| 151°43'22.7"W | | | | |
| | | Daybeacon '2' | 59°29'29.2"N | |
| 151°33'17.2"W | | | | |
| 16646 | 10 th Ed.6/24/89 La | st LNM 24/97 NAD 83 | (BP-156957) | |
| | 25/97 | | , | |
| AK -Ports of Southeastern Cook Inlet | | eastern Cook Inlet | | |
| | delete: | Lighted Buoy '1' | 59°26'51.7"N | |
| 151°4 | 3'25.6"W | | | |
| | add: | Light '1' | 59°26'52.0"N | |
| 151°4 | 3'22.7"W | | | |

Date:17 JUNE 1997

17 JUNE 1997

| 17324 | 13 th Ed. 3/25/89 La 25/97 | ast LNM 37/96 NAD 83 | (CCGD17) |
|-------|------------------------------------------|-------------------------------|--------------|
| | AK - Southeast - Si | itka Sound to Salisbury Sound | |
| | delete: | Lighted Buoy '9' | 57°12'35.1"N |
| 135°2 | 9'44.9"W | | |
| | add: | Light '9' | 57°12'35.2"N |
| 135°2 | 9'45.0"W | | |
| 17327 | 19 th Ed. 2/01/97 La 25/97 | ast LNM 37/96 NAD 83 | (CCGD17) |
| | AK - Southeast - Si | itka Harbor and Approaches | |
| | delete: | Lighted Buoy '9' | 57°03'13.5"N |

135°20'58.6"W

Lighted Buoy '9' delete:

Light '9' 57°03'13.6"N add:

135°20'58.7"W

VI PROPOSED CHANGES IN AIDS TO NAVIGATION

1. The Coast Guard is considering removing the bell from Cap&t. Elias Bell Buoy "2".

Any interested company or individual wishing to provide comments should contact:

Commanding Officer USCGC SWEETBRIER (WLB 405) P.O Box 300 Cordova, AK 99574 Attn: ENS Bird 907-424-3434

VII GENERAL

ALASKA - ALASKA PENINSULA- WATERWAYS ANALYSIS AND MANAGEMENT SYSTEM (WAMS)

- The Coast Guard is conducting a Waterways Analysis and Management System (WAMS) study of thirtkinak Strait Waterway which includesSitkalidak Strait, Geese Channel, Alitak Bay and Moser Bay. The study focuses on the area's aids to navigation system, waterborne commerce, marine casualty information, port/harbor resources, emergency response plans, routine and emergency communication capabilities, and future development projects.
- 2. The Coast Guard is conducting a Waterways Analysis and Management System (WAMS) study of the Alaska Peninsula Waterway which includes the Semidi Islands, Chignik Bay, Sand Point, Korovin Strait, Popof Strait and Unga Strait. The study focuses on the area's aids to navigation system, waterborne commerce, marine casualty information, port/harbor resources, emergency response plans, routine and emergency communication capabilities, and future development projects.

Date:17 JUNE 1997 4

17 JUNE 1997

LOCAL NOTICE TO MARINES NO 25

Any interested company or individual wishing to provide comments or participate in these two user surveys should contact:

Commanding Officer USCGC FIREBUSH (WLB 393) P.O Box 190653 Kodiak, AK 996190653 Attn: WAMS Officer 487-5303

3. The Coast Guard is conducting a Waterways Analysis and Managemen system (WAMS) study of Kachemak Bay. The study focuses on the area's aids to navigation system, waterborne commerce, marine casualty information, port/harbor resources, emergency response plans, routine and emergency communication capabilities, and future development projects. Any interested company or individual wishing to provide comments or participate in this user survey should contact:

Commanding Officer USCGC SEDGE (WLB 402) P.O Box 101 Homer, AK 99603 Attn:ENS C. E. Bland (907) 235-5233

VIII LIGHT LIST CORRECTIONS

Note: * Indicates the column(s) in which a correction has been made or new information added. *

| (1) LLNR | (2) (3) (4) Name and Location | (5) Position | (6) (7) Characteristics | (8) Height | Range | Structure | Remarks |
|-------------|-------------------------------------------------------|-----------------------|----------------------------|---------------|-------|-----------------------|---------|
| N/W | | | | | | | |
| 25030 | Sitka Harbor Channel Light 9 | | QG | 20 | 3 | Pile | |
| | * | 135-21.0 |) | * | | * | |
| 25080 | Light 9 | 57-12.6 135-29.8 | FL G 4s | 30 | 4 | Pile | |
| | * | * | | * | | * | |
| 25485 | Strawberry Channel Entranc Lighted Whistle Buoy SC | e 60-19.3 145-59.8 | Mo (A) W | | 4 | Red and White Stripes | |
| | * | | * | * | | * | |

VIII LIGHT LIST CORRECTIONS (Cont)

17 JUNE 1997

LOCAL NOTICE TO MARINES NO 25

Note: * Indicates the column(s) in which a correction has been made or new information added. *

(4) (2) (3) (5) (6) (8)(1) LLNR Name and Location Position Characteristics Height Range Structure

Remarks

Red nuns and green cans Maintained from

OCT 1. Marks channel

N/W

25615 South Channel May 1 to 25/97

Buoys (about 18)

from Mummy

Island northeastward.

Route requires local knowledge,

extreme caution advised due to

shifting shoals.

25822 Servs Dock Lights (2) 61-07.3 FI R 13 On dolphins 146-20.6 59-26.9 26155 Light 1 FL G 2.5s 4 151-43.4 26185 Daybeacon 2 59-29.5

151-33.3

IX ADDITIONAL ENCLOSURES

NONE

K. A. Hamblett Commander, U.S. Coast Guard Waterways Management and Navigation Safety Branch Seventeenth Coast Guard District By direction of the Commander Operational Excellence Through Leadership, Teamwork And Continuous Improvement

Date:17 JUNE 1997 6 Notice Number 25